

# Canon SERVICE MANUAL REPORT

Serial No. AC10-016

Service Manual

Issued by Service Department, Canon Camera Co., Inc.


Date 24th May, 1965

## REGARDING CHANGED IN CHECKING METHODS FOR SHUTTER RELEASES OF CANON FX AND PELLIX

### 1. CONTENTS

Recently there have been many claims that the shutter does not release even though the shutter button is pressed. The reason for this is that the mirror clamp lever (13-8257) does not get released. Heretofore, the release of the mirror clamp lever was judged good when the difference between how strong the mirror charge lever (19-9553) was set and the weight of the release of the mirror clamp lever was 40 g. However, due to fluctuations in measuring and instability in the checking method, we have changed the checking method as follows:

(New Checking Method)



The mirror clamp lever (13-8257) should come loose when the shutter button is pressed while pressing the A part of mirror charge lever (13-8271) at 200 g with a tension gauge.

### 2. MEASURES TAKEN BY SERVICE DEPARTMENT

Hereafter, the new checking method is to be applied to the service parts also.

### 3. REINFORCEMENT OF NEW PROCESS

Mid-April, 1965

\* \* \*

the end

